


Specifications:


1. Power Input : AC 110 ~ 220V
2. Operating voltage : DC+12V. Approx. 0.5A
3. Operating temperature : 0 °C ~ 45 °C
4. Storage temperature : - 20 °C ~ 60 °C
5. Size : **show in picture 1**



6. Weight : Approx. 2.2Kg (including adaptor)
7. Acceptance speed : Approx. 1 ~3 seconds
8. Acceptance bills : accept the bills around the world such as Taiwan, U.S.A (after 1999 version's bills), Euro,.....etc.

Operation:

- (1) Take this machine out from the box.
- (2) Plug one adaptor with power, another adaptor connect with machine **(as show in picture 1)**



- (3) Place the bill under the screen **(see picture 2)**
- (4) Wait for 1 ~ 3 seconds
- (5) Check the bill image on the screen and compare it with the real bills / pictures **(see left hand side for the real results)**
- (6) Change to stand-by mode automatically as you take the bill away for 8~10 seconds
- (7) Take the adaptor away , as you are not using.

PS. Please put the black sticker over the platform, to reduce the light reflexion. (See picture 3)

Warranty: